## Fa11 1977

## Monitoring - Pesticide Disposal Sites\*

```
Lovelock - Soil
                         (Pershing Co.)
   50' North - None
   50' East - "
   50' South -
   50' West - "
Lovelock - Vegetation
   50' North - .001 DDE; .003 H.E.**
   50' East - None
   50' South - .002 DDE; .003 H.E.
   50' West - .002 H.E.
Lovelock - Water
   (1) Well 1-1/2 miles S.W. - None
   (2) Well 2 miles S.W. - None
Middle Roese Soil
                        (Lander Co.)
   50' North - None
   50' East - "
   50' South - "
   50' West - "
Middle Roese - Vegetation
   50' North - None
   50' East - "
   50' South - "
   50' West - "
Middle Beese - Water
   (1) Powers Domestic Well - None
        2-1/2 miles South
Orovada - Soil
                        (Humboldt Co.)
   50' North - None
   50' East - "
   50' South - .002 Aldrin
   50' West - .001 Aldrin
Orovada - Vegetation
   50' North - .002 DDT
  50' East - .007 DDT
   50' South - None
  50' West - None
```

```
Orovada - Water
(1) Spring 1-3/4 miles S.W. - None
(2) Well 2-1/2 miles S.W. - None

Fallon - Soil (Churchill Co.)
50' North - None
50' East - "
50' South - "
50' West - "

Fallon - Vegetation
50' North - None
50' East - "
50' South - "
50' South - "
50' West - "

Fallon - Water
(1) Well 1 Mile East - None
```

\*Samples taken 10-14-77 & 10-20-77 \*\*H.E. Heptachlor Epoxide \*\*\*Air not sampled at any site.